

DPF Cleaning Report

Customer:	Unipart	Order Number:	
Depot:	Crawley	Ceramex Reference:	ST000005236
Mileage:	120,000	Serial No:	58919
Vehicle Details:	BMW LC 57	Date:	14/10/2013

Back Pressure Testing In kilopascal (kPa) @ 50l/s

Before Clean

14.6

After Clean


1.4

Weight Loss During Cleaning (In grams)

Weight of Ash and Soot removed during cleaning
(Typically, blocked DPFs contain at least 30g)

101

Airflow / Backpressure Curve



DPF Condition Result

The dpf was very well loaded with soot and ash. Post testing points to a very clean dpf with the system working well.



IMPORTANT: Please follow the vehicle manufacturer's guidelines for resetting the ECU when refitting the DPF

203 Bedford Avenue
Slough
SL1 4RY
Tel. +44 (0) 1753 501970
www.ceramex.com

